

street address

18th between Church & Dolores

block number

3579

lot number

6

summary

5

building type/use/number of floors

School / 3 + tower

landmark number

RELATIONSHIP WITH SURROUNDING BUILDINGS

Relationship of

setting to building

-2 -1 0 1 2 3 4 5

Importance as contribution

to a cluster/streetscape

-2 -1 0 1 2 3 4 5

ARCHITECTURAL DESIGN VALUATION

Facade proportions

varies

-2 -1 0 1 2 3 4 5

Richness/Excellence

of detailing/decoration

-2 -1 0 1 2 3 4 5

Unique visual

feature of interest

0 1 2 3 4 5

Example of a rare or

unusual style or design

0 1 2 3 4 5

Overall architectural

quality

-2 -1 0 1 2 3 4 5

☐ PROPOSED FOR FURTHER INVESTIGATION☒ CORNICE, PARAPET, APPENDAGE

Importance of cornice

to building design

-2 -1 0 1 2 3 4 5

Cornice contribution

to streetscape

-2 -1 0 1 2 3 4 5

FACADE CONDITION

Physical condition

-2 -1 0 1 2 3 4 5

Paint/Material

color

-2 -1 0 1 2 3 4 5

☒ REMODELING

Appropriateness

of improvements

-2 -1 0 1 2 3 4 5

generally A-OK

date


Field Notes

The tower, I think, is one of the finest of its kind. The rest works well & hard to keep pace, including the small rear tiled & arcaded tower.

Earthquake proofing nearly done. Building looks better than ever.
9.28.76

Review Notes

Junior League Listing

☐ text ☐ index ☐ file☐ Northern California Guide☐ Other Listing

photo

100-33424

A4

