lot number

building type/use/number of floors

landmark number

RELATIONSHIP WITH SURROUNDING BUILDINGS Relationship of setting to building

-2 -1 0 1 2 3 4 5

Importance as contribution -2 -1 0 1 2 3 4 5 to a cluster/streetscape

ARCHITECTURAL DESIGN VALUATION -2 -1 0 1 2 3 4 5 Facade proportions

Richness/Excellence -2 -1 0 1 2 3 4 5

Unique visual feature of interest

of detailing/decoration

0/12345

Example of a rare or unusual style or design

Overall architectural quality

-2 -1 0 1 2 3 4 5

PROPOSED FOR FURTHER INVESTIGATION

CORNICE, PARAPET, APPENDAGE Importance of cornice

to building design -2 -1 0 1 2 3 4 5

Cornice contribution -2 -1 0 1 2 3 4 5 to streetscape

FACADE CONDITION -2 -1 0 1 2 3 4 5 Physical condition

Paint/Material -2 -1 0 1 2 (3) 4 5 color

REMODELING Appropriateness -2 -1 0 1 2 3 4 5 of improvements

Enfe 4.30-74

Field Notes

Review Notes

Junior League Listing Ttext Dindex Dfile ☐ Northern California Guide Other Listing

