Paint/Material

color

landmark number

-2 -1 0 1 2 3 4 5

building type/use/number of floors

RELATIONSHIP WITH SURROUNDING BUILDINGS Relationship of

setting to building -2 -1 0 1/2 3 4 5

Importance as contribution -2 -1 0 1 2 3 4 5 to a cluster/streetscape

ARCHITECTURAL DESIGN VALUATION -2 -1(0) 1 2 3 4 5 Facade proportions


Richness/Excellence of detailing/decoration -2 -1 0 (1)2 3 4 5

Unique visual 0 1 2 3 4 5 feature of interest

Example of a rare or 0 1 2 3 4 5 unusual style or design

Overall architectural quality

-2 -1 0 1 2 3 4 5



LIPROPOSED FOR FURTHER IN	VE	STI	GA:	TION		
CORNICE, PARAPET, APPER	2					
to building design	-2	-1	0	1 2 3	)4	5
Cornice contribution to streetscape	-2	-1	0	1(2)3	4	5
FACADE CONDITION Physical condition	-2	-1	0	1/2/3	4	5

REMODELING extra service door Appropriateness -2 -1 0 1 2 3 4 5 of improvements

Engl. 8-76 date

row of griffins & preachers', pulpit centered. "bother" Jacobellian

Review Notes

Junior	League Listing	
	☐index ☐file	
	Northern California Guide	
	Other Listing	