151/3 Liberty St

street address

3607	36A	1
block number	lot number	summary

R/2

building type/use/number of floors

landmark number

RELATIONSHIP WITH SURROUNDING BUILDINGS

Relationship of setting to building: -2 -1 0 1 2 (3) 4 5

Importance as contribution to a cluster/streetscape: -2 -1 (0) 1 2 3 4 5

ARCHITECTURAL DESIGN VALUATION

Facade proportions: -2 (-1) 0 1 2 3 4 5

Richness/Excellence of detailing/decoration: -2 -1 (0) 1 2 3 4 5

Unique visual *feature* of interest: 0 (1) 2 3 4 5

Example of a rare or unusual style or design: (0) 1 2 3 4 5

Overall architectural quality: -2 -1 (0) 1 2 3 4 5

☐ PROPOSED FOR FURTHER INVESTIGATION

☐ CORNICE, PARAPET, APPENDAGE

Importance of cornice to building design: -2 -1 0 1 2 3 4 5

Cornice contribution to streetscape: -2 -1 0 1 2 3 4 5

FACADE CONDITION

Physical condition: -2 -1 0 (1) 2 3 4 5

Paint/Material color: -2 -1 0 1 2 (3) 4 5

☐ REMODELING

Appropriateness of improvements: -2 -1 0 1 2 3 4 5

KOTAS 9/11

date

Field Notes

Again, scaled properly but otherwise pulled up by neighboring buildings.

Eight or teens bungalow

Review Notes

Junior League Listing

☐ text ☐ index ☐ file

☐ Northern California Guide

☐ Other Listing _____

42/33 photo 13-33

C5