

PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code _____

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource name(s) or number (assigned by recorder) 251 Waller Street.

1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a. County: San Francisco

and (P2b and P2c or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad: San Francisco North, Calif. Date: 1956 (rev. 1973)

*c. Address: 251 Waller Street. City: San Francisco Zip: 94102

d. UTM: Zone: 10 mE/ _____ mN (G.P.S.)

e. Other Locational Data: Assessor's Parcel Number (Map, Block, Lot): 0869-034

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries.)

251 Waller Street is located on a 25' x 137' lot on the south side of Waller Street, between Buchanan and Webster Streets. Built ca. 1890, 251 Waller Street is a 3-story, wood frame, single family building designed in the Stick/Eastlake style. The rectangular shaped building is clad in wood drop siding and is capped by a flat roof. The primary façade faces north and is 3 bays wide. The ground story contains a below-grade garage and pedestrian door in the left bay. Both doors have pilaster surrounds and dentil cornices. In the right bay, wood steps lead to an entry portico with Corinthian columns, paneled frieze, and roof balustrade on the first story. The portico shelters a single recessed glazed, wood entry door with transom. The center bay of the first story contains a squared bay window with Corinthian pilasters and center colonnette and paneled frieze. The window and portico have a continuous modillion cornice. The left bay contains a flush window with pilaster surround, missing its capitals. The second story contains a flush window Corinthian pilaster surrounds and pedimented cap in the right bay. The center bay has squared bay window with similar decoration to the first-story bay window and arched sash. The left bay contains a flush window with pilaster surround, missing its capitals, and arched sash. All windows have undivided, wood, double hung sash. The façade terminates with a panel frieze and bracketed cornice on the center and right bays. The left bay has a modest cornice. The building appears to be in good condition and contributes to the Hayes Valley Residential Historic District (see DPR 523 D form).

*P3b. Resource Attributes: (list attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other



P5b. Photo: (view and date)

View from north
8/29/2006

*P6. Date Constructed/Age and

Sources: ☒ Historic
1900, ca. 1890
SF Assessor, Sanborn maps

*P7. Owner and Address:

251 Waller LLC
50 Otis St
San Francisco, CA

*P8. Recorded by:

Page & Turnbull, Inc.
724 Pine Street
San Francisco, CA 94108

*P9. Date Recorded:

8/29/2006

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none") None

*Attachments: ☒ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record
☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photograph Record ☐ Other (list)