summary

building type/use/number of floors

landmark number

RELATIONSHIP WITH SURROUNDING BUILDINGS

Relationship of setting to building

-2 -1 0 1 2 3 4 5

Importance as contribution to a cluster/streetscape

-2 -1 0 1 2/3

ARCHITECTURAL DESIGN VALUATION

-2 -1 0/1 2 3 4 5 Facade proportions

Richness/Excellence of detailing/decoration

-2 -1 0/1/2 3 4 5

Unique visual feature of interest

0 1 2 3 4 5

Example of a rare or unusual style or design

Overall architectural quality

-2 -1 0 1 2 3 4 5

PROPOSED FOR FURTHER INVESTIGATION

CORNICE, PARAPET, APPENDAGE

Importance of cornice

to building design -2 -1 0 1 2 3 4 5

Cornice contribution

-2 -1 0 1 2 3 4 5 to streetscape

FACADE CONDITION

-2 -1 0 1 2 (3) 4 5 Physical condition

Paint/Material

-2 -1 0 1 2 3 4 5 color

REMODELING

Appropriateness of improvements

-2 -1 0 1 2 3 4 5

Engle 7-1-76 date

Field Notes

15

ARCH:

ROUSSEAU + ROUSSEAU

Review Notes

Junior League Listing

Ttext ☐ index ☐ file

Northern California Guide

Other Listing _

