

STRUCTURES OF MERIT

BLOCK 317 LOT 1  
ADDRESS 501 GEARY  
NAME HOTEL BELLEVUE  
HERITAGE SURVEY RATING \_\_\_\_\_  
1976 INVENTORY RATING 3/4



501-515 Geary  
street address

317  
block number

1  
lot number

4  
summary

hotel-7  
building type/use/number of floors

landmark number

RELATIONSHIP WITH SURROUNDING BUILDINGS

Relationship of setting to building -2 -1 0 1 2 3 4 5  
Importance as contribution to a cluster/streetscape -2 -1 0 1 2 3 4 5

ARCHITECTURAL DESIGN VALUATION

Facade proportions -2 -1 0 1 2 3 4 5  
Richness/Excellence of detailing/decoration -2 -1 0 1 2 3 4 5  
Unique visual *dormers* feature of interest 0 1 2 3 4 5  
Example of a rare or unusual style or design 0 1 2 3 4 5  
Overall architectural quality -2 -1 0 1 2 3 4 5

PROPOSED FOR FURTHER INVESTIGATION

CORNICE, PARAPET, APPENDAGE  
Importance of cornice to building design -2 -1 0 1 2 3 4 5  
Cornice contribution to streetscape -2 -1 0 1 2 3 4 5

FACADE CONDITION

Physical condition -2 -1 0 1 2 3 4 5  
Paint/Material color -2 -1 0 1 2 3 4 5

REMODELING *awning stripes go the wrong way*  
Appropriateness of improvements -2 -1 0 1 2 3 4 5

*Engle 7-15-76*  
date

Field Notes

*Good recent paint job -*

ARCH: N.W. SEXTON  
see: CHRONICLE, 11 JUN 1910, p.11



photo

Review Notes

Junior League Listing  
 text  index  file  
 Northern California Guide  
 Other Listing \_\_\_\_\_

DI

