

2121-2127 FILLMORE
street address Santa Clara Apts.

635
block number

3
lot number

D
summary

R/3 c ground
building type/use/number of floors

landmark number

RELATIONSHIP WITH SURROUNDING BUILDINGS
 Relationship of setting to building -2 -1 0 1 (2) 3 4 5
 Importance as contribution to a cluster/streetscape -2 -1 0 1 (2) 3 4 5

ARCHITECTURAL DESIGN VALUATION
 Facade proportions -2 -1 0 (1) 2 3 4 5
 Richness/Excellence of detailing/decoration -2 -1 0 1 (2) 3 4 5
 Unique visual feature of interest 0 (1) 2 3 4 5
 Example of a rare or unusual style or design 0 (1) 2 3 4 5
 Overall architectural quality -2 -1 0 (1) 2 3 4 5

PROPOSED FOR FURTHER INVESTIGATION

CORNICE, PARAPET, APPENDAGE
 Importance of cornice to building design -2 -1 0 1 2 3 4 5
 Cornice contribution to streetscape -2 -1 0 1 2 3 4 5

FACADE CONDITION
 Physical condition -2 -1 0 1 2 3 4 5
 Paint/Material color -2 -1 0 1 2 3 4 5

REMODELING
 Appropriateness of improvements -2 -1 0 1 2 3 4 5

11-6-75 79.
date

Field Notes



Review Notes

Junior League Listing
 text index file
 Northern California Guide
 Other Listing _____

photo 103 - 18