

1326 Park street address      668 block number      5 lot number      1 summary

C-1 building type/use/number of floors      landmark number

**RELATIONSHIP WITH SURROUNDING BUILDINGS**  
 Relationship of setting to building      -2 -1 0 1 (2) 3 4 5  
 Importance as contribution to a cluster/streetscape      -2 -1 0 1 (2) 3 4 5

**ARCHITECTURAL DESIGN VALUATION**  
 Facade proportions      -2 -1 0 (1) 2 3 4 5  
 Richness/Excellence of detailing/decoration      -2 -1 0 (1) 2 3 4 5  
 Unique visual feature of interest      (0) 1 2 3 4 5  
 Example of a rare or unusual style or design      (0) 1 2 3 4 5  
 Overall architectural quality      -2 -1 0 (1) 2 3 4 5

PROPOSED FOR FURTHER INVESTIGATION

CORNICE, PARAPET, APPENDAGE  
 Importance of cornice to building design      -2 -1 0 1 2 3 4 5  
 Cornice contribution to streetscape      -2 -1 0 1 2 3 4 5

**FACADE CONDITION**  
 Physical condition      -2 -1 0 1 2 (3) 4 5  
 Paint/Material color      -2 -1 0 1 2 (3) 4 5

REMODELING  
 Appropriateness of improvements      -2 -1 (0) 1 2 3 4 5

Engle 8.11.74 date

Field Notes



photo 297.24

Review Notes

Junior League Listing  
 text     index     file  
 Northern California Guide  
 Other Listing \_\_\_\_\_

F1