street address

building type/use/number of floors

landmark number

RELATIONSHIP WITH SURROUNDING BUILDINGS Relationship of

setting to building

-2 -1 0 1/2 3 4 5

Importance as contribution to a cluster/streetscape -2 -1 0 12 3 4 5

ARCHITECTURAL DESIGN VALUATION

-2 -1 0 1 2 3 4 5 Facade proportions

Richness/Excellence

-2 -1 0 (1 2 3 4 5 of detailing/decoration

Unique visual

feature of interest

0(1)2 3 4 5

Example of a rare or unusual style or design

0 1(2)3 4 5

Overall architectural quality

-2 -1 (0) 1 2 3 4 5

PROPOSED FOR FURTHER INVESTIGATION

CORNICE, PARAPET, APPENDAGE

Importance of cornice

to building design -2 -1 0 1 2 3 4 5

Cornice contribution

-2 -1 0 1 2 3 4 5 to streetscape

FACADE CONDITION

Physical condition -2 -1 0 1 2 3 4 5

Paint/Material

color -2 -1 0 1 2 3 4 5

REMODELING

Appropriateness of improvements

-2 (-1)0 1 2 3 4 5

HC 9-19-76

messed up bldg, included here as a part of an important row



Review Notes

Junior League Listing

index file text

Northern California Guide

Other Listing