wilding type/use/number of floors

landmark number

RELATIONSHIP WITH SURROUNDING BUILDINGS

Relationship of setting to building

-2 -1 0 1 2 3 4 5

Importance as contribution

-2 -1 0 1 2 (3/4 5 to a cluster/streetscape

ARCHITECTURAL DESIGN VALUATION

-2 -1 0 1 2 (3) 4 5 Facade proportions

Richness/Excellence

-2 -1 0 1 2 (3) 4 5 of detailing/decoration

Unique visual

0 1 2 (3) 4 5 feature of interest

Example of a rare or unusual style or design

0 1 2 3 4 5

Overall architectural

-2 -1 0 1 2(3)4 5 quality

PROPOSED FOR FURTHER INVESTIGATION

CORNICE, PARAPET, APPENDAGE

Importance of cornice

-2 -1 0 1 2 3 4 5 to building design

Cornice contribution

-2 -1 0 1 2 3 4 5 to streetscape

FACADE CONDITION

Physical condition -2 -1 0 1 2 3 4 5

Paint/Material

-2 -1 0 1 2 3 4 5 color

REMODELING

Appropriateness

-2 -1 0 1 2 3 4 5 of improvements

79 6/13/15

Field Notes

huge overlanging roof



Review Notes

Junior League Listing

☐text ☐index ☐file

Northern California Guide

Other Listing



view flooting west on Hight