

75 Beaver street address 3541 41 2
 block number lot number summary

R.1 building type/use/number of floors landmark number

RELATIONSHIP WITH SURROUNDING BUILDINGS

Relationship of setting to building -2 -1 0 1 2 3 4 5
 Importance as contribution to a cluster/streetscape -2 -1 0 1 2 3 4 5

PROPOSED FOR FURTHER INVESTIGATION

CORNICE, PARAPET, APPENDAGE
 Importance of cornice to building design -2 -1 0 1 2 3 4 5
 Cornice contribution to streetscape -2 -1 0 1 2 3 4 5

ARCHITECTURAL DESIGN VALUATION

Facade proportions -2 -1 0 1 2 3 4 5
 Richness/Excellence of detailing/decoration -2 -1 0 1 2 3 4 5
 Unique visual feature of interest 0 1 2 3 4 5
 Example of a rare or unusual style or design 0 1 2 3 4 5
 Overall architectural quality -2 -1 0 1 2 3 4 5

FACADE CONDITION
 Physical condition -2 -1 0 1 2 3 4 5
 Paint/Material color -2 -1 0 1 2 3 4 5
 REMODELING
 Appropriateness of improvements -2 -1 0 1 2 3 4 5

Engle 8.20.74
 date

Field Notes

Review Notes

Junior League Listing
 text index file
 Northern California Guide
 Other Listing _____



photo 322.31

BA