building type/use/number of floors

landmark number

RELATIONSHIP WITH SURROUNDING BUILDINGS

Relationship of setting to building

-2 -1 0 1 2/3 4 5

Importance as contribution to a cluster/streetscape

-2 -1 0 1 2 3 4 5

ARCHITECTURAL DESIGN VALUATION

Facade proportions

-2 -1 0 1 2 3 4 5

Richness/Excellence of detailing/decoration

-2 -1 0 1 2 3 4 5

Unique visual feature of interest

0/1 2 3 4 5

Example of a rare or unusual style or design

0/12345

Overall architectural quality

-2 -1 0 1 2 3 4 5

PROPOSED FOR FURTHER INVESTIGATION

CORNICE, PARAPET, APPENDAGE

Importance of cornice

to building design -2 -1 0 1 2 3 4 5

Cornice contribution

-2 -1 0 1 2 3 4 5 to streetscape

FACADE CONDITION

-2 -1 0 1/2 3 4 5 Physical condition

Paint/Material color


-2 -1 0 1 2 3 4 5

REMODELING

MODELING
Appropriateness
-2 -1 0 1 2 3 4 5

Engle 8.74

Field Notes



Review Notes

Junior League Listing

Ttext | index | file

Northern California Guide

Other Listing